

DATE 0807Z 06 DEC 62

SECRET

TO DIRECTOR
25X1A

FROM [REDACTED]

INFO OSA (1-2-3-4-5-6-7-8-9-10-11-12-13-14-15)

INFO S/C (16)

ROUTINE

25X1A

TOR: 0852Z 06 DEC 62

IN 58281

TO

[REDACTED]

INFO

(3201)

FROM

[REDACTED]

25X1A

A MINOR PROBLEM WAS ENCOUNTERED ON MSN 3201 DURING FUEL TRANSFER IN AIR REFUELING OPERATIONS BETWEEN KC-135 AND ARTICLE. FUEL TRANSFER INDICATIONS SHOWED ABNORMALLY SLOW TRANSFER BUT A THOROUGH CHECK OF BOTH SYSTEMS ON 6 DEC SHOWED KC-135 FUEL COUNTER TO BE IN ERROR. THIS IS NOT A PROBLEM DUE TO BACK UP INDICATION OF FUEL QUANTITY GAGE WHICH WILL GIVE ACCURATE READING OF AMOUNT OFF LOADED.

END OF MESSAGE

SECRET

GROUP 1
Excluded from automatic
downgrading and
declassification